Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLD **Project Name:** 

Project Code: Observation ID: 1 Site ID: 270

Agency Name: **QLD Department of Primary Industries** 

Site Information

Desc. By: M. DeCorte Locality:

Date Desc.: Elevation: 20/06/91 300 metres Map Ref.: Sheet No.: 8157 GPS Rainfall: No Data Northing/Long.: 7763010 AMG zone: 55 Runoff: Verv slow 431206 Datum: AGD66 Well drained Easting/Lat.: Drainage:

Geology

ExposureType: Conf. Sub. is Parent. Mat.: No Data No Data **Substrate Material:** Geol. Ref.: No Data No Data

**Land Form** 

Rel/Slope Class: Undulating rises 9-30m 3-10% Pattern Type: Rises Relief: No Data

Morph. Type: Elem. Type: Very gently sloped Slope Category: Plain

% Aspect: No Data Slope:

Surface Soil Condition (dry):

**Erosion:** 

**Soil Classification** 

Australian Soil Classification: N/A Mapping Unit: Haplic Eutrophic Red Chromosol Medium Non-gravelly Clav-Principal Profile Form: Dr2.12

loamy Clayey Moderately deep

**ASC Confidence:** Non-calcic brown **Great Soil Group:** 

No analytical data are available but confidence is fair. soil

Site Disturbance: No effective disturbance other than grazing by hoofed animals

Vegetation:

**Surface Coarse Fragments:** 

**Profile Morphology** 

0 - 0.1 m Reddish brown (5YR4/4-Moist); ; Sandy clay loam (Heavy); Weak grade of structure, 20-50

mm, Angular blocky; Smooth-ped fabric; Dry; Very firm consistence; , Calcareous, , ; ,

Gypseous, , ; Field pH 6 (Raupach, 0.05); Clear, Smooth change to -

B21 0.1 - 0.5 m Red (2.5YR4/6-Moist); ; Light clay; Strong grade of structure, 10-20 mm, Angular blocky;

Smooth-ped fabric; Moderately moist; Very firm consistence; Many cutans, >50% of ped faces or walls coated, prominent; , Calcareous, , ; , Gypseous, , ; Field pH 7 (Raupach, 0.3); Clear,

Smooth change to -

ВЗ 0.5 - 0.75 m Red (2.5YR4/8-Moist); ; Light clay; Strong grade of structure, 20-50 mm, Angular blocky;

Smooth-ped fabric; Moderately moist; Very firm consistence; Many cutans, >50% of ped faces

or walls coated, prominent; , Calcareous, , ; , Gypseous, , ; Field pH 7 (Raupach, 0.6);

**Morphological Notes** 

**Observation Notes** 

**Site Notes** 

Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLD DLR Site ID: 270 Observation ID: 1

DLR Site ID: 270
QLD Department of Primary Industries

Project Name: Project Code: Agency Name:

## **Laboratory Test Results:**

Depth m	рН	1:5 EC dS/m		angeable Ig	Cations K	Na Cmol (+)/	cchangeable Acidity kg	CEC	ECE	ESP
Depth	CaCO3	Organic C	Avail. P	Total P	Total N	Total K	Bulk Density		ticle Size CS FS	Analysis Silt Clay
m	%	%	mg/kg	%	%	%	Mg/m3	GV	% %	Sill Clay
Donth	COLE		Cravit	(\ / -	14.: 18.	/ater Conte			l/ oot	V umant
Depth m	COLE	Sat.		0.1 Bar	umetric w 0.5 Bar j - m3/m3	1 Bar		Bar	K sat mm/h	K unsat mm/h

Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLD DLR Site ID: 270 Observation ID: 1

Project Name: Project Code: Agency Name: DLR Site ID: 270
QLD Department of Primary Industries

**Laboratory Analyses Completed for this profile**