Project Name:Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLDProject Code:DLRSite ID:1324Observation ID:1Agency Name:QLD Department of Primary Industries

Site	Info	rmation
Onco		mation

Desc. I Date D Map Re Northin Easting <u>Geolo</u>	Site information Desc. By: Rogers, Gary Date Desc.: 05/08/92 Map Ref.: Sheet No. : 8059 Shorthing/Long.: 7886300 Additional Content of State 363635 Date Desc.: 363635 Desc.: 363635			Locality: Elevation: Rainfall: Runoff: Drainage:		No Data No Data Slow Well drained				
Geol. F				Conf. Sub. is Parent. Mat.: Substrate Material:			No Data Undisturbed soil core, No Data			
Land Rel/Slo	Form ope Class:	Gentl 1-3%	y undulating plains <9m	Pattern Type:	Pattern Type: Alluvia		plain			
Morph. Elem. 1 Slope:	Туре:	Flat Plain 2 %		Relief: Slope Categor Aspect:	y:	No Data Very gent No Data	ly sloped	3		
Erosic			on (dry): Hardsetting							
Austra Haplic I	lassificati lian Soil Cl Eutrophic Bi y Deep	assific	cation: Chromosol Thick Non-gravel		•••	ng Unit: al Profile	Form:	N/A Dr2.22		
ASC C No ana	confidence: alytical data	are av	vailable but confidence is fai	ir.		Soil Group d animals	c	Red podzolic soil		
Vegetation: Low Strata - Tussock grass, 0.51-1m, Sparse. *Species includes - Heteropogon contortus, Bothriochloa decipiens, Chrysopogon fallax Mid Strata - , , . *Species includes - None recorded										
Tall Strata - Tree, 20.01-35m, Very sparse. *Species includes - Eucalyptus crebra Surface Coarse Fragments: No surface coarse fragments										
<u>Profile</u> A11	e Morphol 0 - 0.04 m							structure; Earthy fabric; Dry; ach, 0.02); Abrupt change to		
A2	A2 0.04 - 0.15 m Dark brown (7.5YR3/4-Moist); ; Fine sandy loam; Massive grade of structure; Earthy fabric; Dry; Firm consistence; , Calcareous, , ; , Gypseous, , ; Field pH 6.5 (Raupach, 0.1); Clear change to									
A3	0.15 - 0.4	m	Dark brown (7.5YR3/4-Moist); ; Fine sandy clay loam; Massive grade of structure; Earthy fabric; Few (<1 per 100mm2) Very fine (0.075-1mm) macropores, Dry; Weak consistence; , Calcareous, , ; , Gypseous, , ; Field pH 6.5 (Raupach, 0.3); Clear change to -							
B2	0.4 - 1.3 r	n	Strong brown (7.5YR4/6-Moist); ; Fine sandy light medium clay; Moderate grade of structure, 20- 50 mm, Subangular blocky; Smooth-ped fabric; Common (1-5 per 100mm2) Very fine (0.075- 1mm) macropores, Strong consistence; , Calcareous, , ; , Gypseous, , ; Field pH 7 (Raupach,							
	nological N									
Obser	vation No	tes								

Site Notes

Project Name:Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLDProject Code:DLRSite ID:1324Observation ID:1Agency Name:QLD Department of Primary Industries

Laboratory Test Results:

Depth	pН	1:5 EC	Excha Ca M	angeable (Cations K	Ex: Na	changeable Acidity	CEC	ECEC	ESP
m		dS/m	Ca W	y	n	Cmol (+)/k				%
0 - 0.04 0.15 - 0.4 0.4 - 1.3	6.4A 6.4A 7A									
Depth m	CaCO3 %	Organic C %	Avail. P mg/kg	Total P %	Total N %	Total K %	Bulk Density Mg/m3	Partic GV C		Analysis Silt Clay
0 - 0.04 0.15 - 0.4 0.4 - 1.3										
Depth	COLE		Gravimetric/Volumetric Water Contents						K sat	K unsat
m		Sat.	0.05 Bar		0.5 Bar - m3/m3	1 Bar	5 Bar 15	Bar I	nm/h	mm/h
0 - 0.04 0.15 - 0.4 0.4 - 1.3										

Project Name:Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLDProject Code:DLRSite ID:1324Observation ID:1Agency Name:QLD Department of Primary Industries

Laboratory Analyses Completed for this profile

4A1 pH of 1:5 soil/water suspension