Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLD **Project Name:**

Project Code: Site ID: 1803 Observation ID: 1

Agency Name: QLD Department of Primary Industries

Site Information

Locality: M.G. Cannon

Desc. By: Date Desc.: Elevation: 24/05/93 No Data Sheet No.: 8255 GPS Map Ref.: Rainfall: No Data Northing/Long.: 7668602 AMG zone: 55 Runoff: No Data Easting/Lat.: 471986 Datum: AGD66 Drainage: No Data

Geology

ExposureType: No Data Conf. Sub. is Parent. Mat.: No Data Geol. Ref.: Substrate Material: No Data No Data

Land Form

Rel/Slope Class: Level plain <9m <1% Pattern Type: Plain Morph. Type: Elem. Type: Flat Relief: No Data Levee **Slope Category:** Level No Data Slope: 1 % Aspect:

Surface Soil Condition (dry): Hardsetting

Erosion:

Soil Classification

Australian Soil Classification: Mapping Unit: N/A Basic Fluvic Orthic Tenosol Thick Non-gravelly Sandy Sandy **Principal Profile Form:** Uc5.11

Very deep

ASC Confidence: Earthy sand **Great Soil Group:**

Analytical data are incomplete but reasonable confidence.

Site Disturbance: Limited clearing, for example selective logging

Vegetation:

Surface Coarse Fragments:

Profile Morphology

A11	0 - 0.1 m	Brown (10YR4/3-Moist); ; Clayey sand; Massive grade of structure; Earthy fabric; Dry; Very weak consistence; , Calcareous, , ; , Gypseous, , ; Field pH 6 (Raupach, 0.05);
A12	0.1 - 0.5 m	Yellowish brown (10YR5/6-Moist); ; Clayey sand; Massive grade of structure; Earthy fabric; Dry; Very weak consistence; , Calcareous, , ; , Gypseous, , ; Field pH 7 (Raupach, 0.3);
B1	0.5 - 0.8 m	Brown (7.5YR5/4-Moist); ; Clayey sand; Massive grade of structure; Earthy fabric; Dry; Very weak consistence; , Calcareous, , ; , Gypseous, , ; Field pH 7 (Raupach, 0.6);
B2	0.8 - 1.2 m	Strong brown (7.5YR5/6-Moist); ; Clayey sand; Single grain grade of structure; Sandy (grains prominent) fabric; Dry; Loose consistence; , Calcareous, , ; , Gypseous, , ; Field pH 7 (Raupach, 1.2);

Morphological Notes

Observation Notes

Site Notes

Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLD DLR Site ID: 1803 Observation ID: 1

Project Name: Project Code: Agency Name: DLR Site ID: 1803
QLD Department of Primary Industries

Laboratory Test Results:

Depth	pН	1:5 EC	Exchangeable Cations			Exchangeable		CEC		ECEC		ESP
m		dS/m	Ca M	9	К	Na Cmol (+)/k	Acidity (g					%
Depth	CaCO3	Organic	Avail. P	Total P	Total N	Total K	Bulk		rticle CS	Size FS	Analysi	
m	%	С %	mg/kg	%	%	%	Density Mg/m3	GV	US.	гэ %	Silt	Clay
Depth	COLE		Gravimetric/Volumetric Water Contents K sa							at	K unsa	ıt
m		Sat.		0.1 Bar	0.5 Bar - m3/m3	1 Bar		Bar	mm		mm/h	

Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLD DLR Site ID: 1803 Observation ID: 1 QLD Department of Primary Industries

Project Name: Project Code: Agency Name:

Laboratory Analyses Completed for this profile