Project Name: Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLD

Project Code: DLR Site ID: 2068 Observation ID: 1

Agency Name: QLD Department of Primary Industries

Site Information

Desc. By: Rogers, Gary Locality:

Date Desc.:11/06/93Elevation:No DataMap Ref.:Sheet No.: 8255GPSRainfall:No DataNorthing/Long.:7631712 AMG zone: 55Runoff:Very slow

Easting/Lat.: 448843 Datum: AGD66 Drainage: Moderately well drained

Geology

ExposureType: No Data Conf. Sub. is Parent. Mat.: No Data

Geol. Ref.: No Data Substrate Material: Undisturbed soil core, No Data

Land Form

Rel/Slope Class: Gently undulating plains <9m Pattern Type: Alluvial plain

1-3%

Morph. Type:FlatRelief:No DataElem. Type:PlainSlope Category:LevelSlope:1 %Aspect:No Data

Surface Soil Condition (dry): Hardsetting

Erosion:

Soil Classification

Australian Soil Classification:Mapping Unit:N/ABleached Eutrophic Brown Chromosol Thick Non-gravellyPrincipal Profile Form:Dy2.42

Loamy Clayey Deep

ASC Confidence: Great Soil Group: No suitable group

No analytical data are available but confidence is fair.

Site Disturbance: No effective disturbance other than grazing by hoofed animals

Vegetation: Low Strata - Tussock grass, 0.51-1m, Mid-dense. *Species includes - Aristida species

Mid Strata - Tree, 3.01-6m, Sparse. *Species includes - Melaleuca species, Eremophila mitchellii, Erythroxylon

australe

Tall Strata - Tree, 6.01-12m, Sparse. *Species includes - Eucalyptus brownii, Acacia argyrodendron, Eucalyptus

papuana

Surface Coarse Fragments: No surface coarse fragments

Profile Morphology

A1 0 - 0.1 m Dark brown (10YR3/3-Moist); ; Sandy loam (Heavy); Massive grade of structure; Earthy fabric; Dry; Firm consistence; , Calcareous, , ; , Gypseous, , ; Field pH 6.5 (Raupach, 0.05); Clear change to
A2e 0.1 - 0.3 m Yellowish brown (10YR5/4-Moist); ; Sandy clay loam (Light); Massive grade of structure; Earthy fabric; Dry; Very firm consistence; , Calcareous, , ; , Gypseous, , ; Field pH 6 (Raupach, 0.2); Abrupt change to
B2 0.3 - 1.5 m Light olive brown (2.5Y5/4-Moist); ; Sandy light clay; Dry; 2-10%, medium gravelly, 6-20mm, subrounded, Quartz, coarse fragments; , Calcareous, , ; , Gypseous, , ; Field pH 7 (Raupach, 1.3);

Morphological Notes

Observation Notes

Site Notes

Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLD DLR Site ID: 2068 Observation ID: 1 QLD Department of Primary Industries

Project Name: Project Code: Agency Name:

Laboratory Test Results:

Depth m	рН	1:5 EC	Exchangeable Ca Mg		Cations K	Exchangeable Na Acidity Cmol (+)/kg		CEC		ECEC		ESP %
Depth	CaCO3	Organic	Avail.	Total	Total	Total	Bulk	Particle		Size	Analysis	
		С	Р	Р	N	K	Density	G۷	cs	FS	Silt	Clay
m	%	%	mg/kg	%	%	%	Mg/m3			%		
Depth	COLE		Gravimetric/Volumetric Water Contents						Ks	at	K uns	at
		Sat.	0.05 Bar		0.5 Bar	1 Bar	5 Bar 15	Bar				
m			g/g - m3/m3 mm/h								mm/l	h

Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLD DLR Site ID: 2068 Observation ID: 1 QLD Department of Primary Industries

Project Name: Project Code: Agency Name:

Laboratory Analyses Completed for this profile