Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLD **Project Name:**

Project Code: Observation ID: 1 Site ID: 2113

Agency Name: QLD Department of Primary Industries

Site Information

M.G. Cannon Locality:

Desc. By: Date Desc.: 06/10/93 Elevation: No Data Sheet No.: 7858 GPS Map Ref.: Rainfall: No Data Northing/Long.: 7789114 AMG zone: 55 Runoff: No Data 271544 Datum: AGD66 No Data Easting/Lat.: Drainage:

Geology

ExposureType: No Data Conf. Sub. is Parent. Mat.: No Data **Substrate Material:** No Data Geol. Ref.: No Data

Land Form

Rel/Slope Class: Gently undulating plains <9m Pattern Type: Alluvial plain

1-3%

Flat Morph. Type: Relief: No Data

Very gently sloped Elem. Type: Plain Slope Category: 1 % Aspect: No Data Slope:

Surface Soil Condition (dry): Hardsetting

Erosion:

Soil Classification

Australian Soil Classification: Mapping Unit: N/A Dy2.43 Calcic Mottled-Subnatric Grey Sodosol **Principal Profile Form: ASC Confidence: Great Soil Group:** Solodic soil

No analytical data are available but confidence is fair.

<u>Site Disturbance:</u> No effective disturbance other than grazing by hoofed animals

Vegetation: Low Strata - Tussock grass, 0.51-1m, Sparse. *Species includes - Aristida species

Mid Strata - Tree, 6.01-12m, Sparse. *Species includes - Eucalyptus brownii Tall Strata - Tree, 12.01-20m, Sparse. *Species includes - Eucalyptus brownii

Surface Coarse Fragments: No surface coarse fragments

Profile Morphology

A11	0 - 0.02 m	Greyish brown (10YR5/2-Moist); ; Fine sandy clay loam; Massive grade of structure; Earthy fabric; Dry; Weak consistence; , Calcareous, , ; , Gypseous, , ; Field pH 6 (Raupach, 0);
A2e	0.02 - 0.12 m	Greyish brown (10YR5/2-Moist); ; Sandy clay loam; Massive grade of structure; Earthy fabric; Dry; Weak consistence; , Calcareous, , ; , Gypseous, , ; Field pH 6 (Raupach, 0.1);
B21	0.12 - 0.5 m	Greyish brown (10YR5/2-Moist); Mottles, 10YR58, 2-10%, 0-5mm, Distinct; Mottles, 2-10%; Medium heavy clay; Moderate grade of structure, 50-100 mm, Columnar; Smooth-ped fabric; Dry; Very strong consistence; , Calcareous, , ; , Gypseous, , ; Field pH 6 (Raupach, 0.4);
B22	0.5 - 0.6 m	Greyish brown (10YR5/2-Moist); ; Medium heavy clay; Moderate grade of structure, 20-50 mm, Angular blocky; Smooth-ped fabric; Dry; Very strong consistence; , Calcareous, , ; , Gypseous, , ; Field pH 7 (Raupach, 0.6);
B23c	0.6 - 0.7 m	Pale brown (10YR6/3-Moist); ; Medium heavy clay; 20-50 mm, Angular blocky; Smooth-ped fabric; Dry; Very strong consistence; Few (2 - 10 %), Calcareous, Medium (2 -6 mm), Nodules; , Gypseous, , ; Field pH 9 (Raupach, 0.7);

Morphological Notes

Observation Notes

Site Notes

Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLD DLR Site ID: 2113 Observation ID: 1 QLD Department of Primary Industries

Project Name: Project Code: Agency Name:

Laboratory Test Results:

Depth m	pН	1:5 EC dS/m	Exchangeable Ca Mg		Cations K	Exchangeable Na Acidity Cmol (+)/kg		CEC		ECEC		ESP %
Depth	CaCO3	Organic	Avail.	Total	Total	Total	Bulk	Pa	article	Size	Analys	is
m	%	C %	P mg/kg	P %	N %	K %	Density Mg/m3	GV	CS	FS %	Silt	Clay
Depth	COLE		Gravimetric/Volumetric Water Contents K sat							at	K uns	at
m		Sat.	0.05 Bar						mm	ı/h	mm/l	ı

Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLD DLR Site ID: 2113 Observation ID: 1 QLD Department of Primary Industries

Project Name: Project Code: Agency Name:

Laboratory Analyses Completed for this profile