Project Name: Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLD

Project Code: DLR Site ID: 492 Observation ID: 1

Agency Name: QLD Department of Primary Industries

Site Information

Desc. By: Barry, Earl Locality:

Date Desc.: Elevation: 19/11/91 No Data Map Ref.: Sheet No.: 8256 GPS Rainfall: No Data Northing/Long.: 7694435 AMG zone: 55 Runoff: No Data 461945 Datum: AGD66 Easting/Lat.: Drainage: No Data

Geology

ExposureType: No Data Conf. Sub. is Parent. Mat.: No Data Geol. Ref.: No Data Substrate Material: No Data

Land Form

 Rel/Slope Class:
 Level plain <9m <1%</th>
 Pattern Type:
 Plain

 Morph. Type:
 Flat
 Relief:
 No Data

 Elem. Type:
 Plain
 Slope Category:
 Level

 Slope:
 %
 Aspect:
 No Data

Surface Soil Condition (dry): Cracking, Self-mulching

Erosion:

Soil Classification

Australian Soil Classification:Mapping Unit:N/AEpicalcareous Self-Mulching Black Vertosol Gravelly MediumPrincipal Profile Form:Ug5.1

fine Very fine Shallow

ASC Confidence: Great Soil Group: Black earth

No analytical data are available but confidence is fair.

Site Disturbance: No effective disturbance other than grazing by hoofed animals

Vegetation: Low Strata - Tussock grass, 0.51-1m, Mid-dense. *Species includes - Cenchrus ciliaris

Mid Strata - , , . *Species includes - None recorded

Tall Strata - Tree, 3.01-6m, Very sparse. *Species includes - Eucalyptus papuana, Eucalyptus erythrophloia,

Lysiphillum

carronii

Surface Coarse Fragments: 10-20%, stony, 200-600mm, subrounded, Diorite

Profile Morphology

A 0 - 0.1 m Black (10YR2/1-Moist); ; Heavy clay; Moderate grade of structure, 2-5 mm, Granular; Smooth-

ped fabric; Moist; Firm consistence; , Calcareous, , ; , Gypseous, , ; Gradual change to -

B 0.1 - 0.65 m Black (10YR2/1-Moist); ; Heavy clay; Strong grade of structure, 20-50 mm, Lenticular; Smooth-

ped fabric; Dry; Very strong consistence; Few (2 - 10 %), Calcareous, Coarse (6 - 20 mm),

Nodules; , Gypseous, , ; Soil matrix is Slightly calcareous;

0.65 - 0.75 m ; , Calcareous, , ; , Gypseous, , ;

Morphological Notes
Observation Notes

Site Notes

Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLD DLR Site ID: 492 Observation ID: 1

Project Name: Project Code: Agency Name: DLR Site ID: 492
QLD Department of Primary Industries

Laboratory Test Results:

Depth	рН	1:5 EC	Exchangeable Cation			Ex	CEC		ECEC		ESP	
m		dS/m	Ca M	9	N.	Na Cmol (+)/k	Acidity (g					%
Depth	CaCO3	Organic C	Avail. P	Total P	Total N	Total K	Bulk Density	Pa GV	rticle CS	Size FS	Analysi Silt	s Clay
m	%	%	mg/kg	%	%	%	Mg/m3	٠,	00	%	Oiit	Olay
Depth	COLE		Gravimetric/Volumetric Water Contents							at	K unsa	ıt
m		Sat.	0.05 Bar	0.1 Bar g/g	0.5 Bar j - m3/m3	1 Bar	5 Bar 15	Bar	mm	/h	mm/h	

Preliminary Assessment and Survey of Land Degradation in the Dalrypmle Shire, QLD DLR Site ID: 492 Observation ID: 1

DLR Site ID: 492
QLD Department of Primary Industries

Project Name: Project Code: Agency Name:

Laboratory Analyses Completed for this profile